

FIG. 1




FIG. 2




FIG. 3




FIG. 4

40

40a

40b

40d

40e

40f

40g

40c

END INSPECTION

SET PRIORITY

!

SECTION

XXXX/XX/XX

FUJI ...

123456...

ID#

FRONTAL THORAX

OVERVIEW OF PELVIS

OVERVIEW OF SKULL

...

...

NEW IMAGE

R

RETAKE IMAGE

ADD

DELETE

▲

▼

DETAIL

FILM

NUMBER OF DIVISION

SIZE

AP/PA

QA

AUTO

SHELTER






FIG. 6




0959407 112104

FIG. 7



05582447 442404

FIG. 8



09989407 112401